Release Notes for Cisco Catalyst IR1101, IR1800, IR8140, and IR8340 Routers, IOS XE 26.1.x

© 2026 Cisco and/or its affiliates. All rights reserved.

Cisco Catalyst Rugged Series Routers, IOS XE 26.1.x 3
New software features 3
IOS XE 26.1.2 3
IOS XE 26.1.1 3
New hardware features 5
IOS XE 26.1.2 5
IOS XE 26.1.1 5
Change in behavior 5
IOS XE 26.1.2 5
IOS XE 26.1.1 5
Example: 6
Resolved issues 6
IOS XE 26.1.2 6
IOS XE 26.1.1 7
Open issues 7
IOS XE 26.1.2 7
IOS XE 26.1.1 8
Known issues 8
IOS XE 26.1.2 8
IOS XE 26.1.1 8
Compatibility 8
Supported software packages 10
IOS XE 26.1.2 10
IOS XE 26.1.1 11
Port Naming Conventions 11
Related resources 14
Legal information 16

© 2026 Cisco and/or its affiliates. All rights reserved.

Cisco Catalyst Rugged Series Routers, IOS XE 26.1.x

Cisco IOS XE 26.1.x introduces new features for Cisco Catalyst Rugged Series Routers. Key features include support for P-5GS6-RC-GL PIM, UTD support, device sensors, timing support for 1588-2017 boundary clock, CoA support, segment routing over IPv6, power over Ethernet plus support, and send a UID to identify the unique source when sending GPS coordinates data.

New software features

This section provides a brief description of the new software features introduced in this release.

IOS XE 26.1.2

There are no new software features in this release

IOS XE 26.1.1

Table 1. New software features for Cisco Catalyst Rugged Series Routers, IOS XE 26.1.1

Product Impact	Feature	Description
Security	Resilient Infrastructure	As part of the ongoing commitment to network security, this release introduces secure alternatives to legacy commands. These updates are designed to mitigate potential risks and assist in establishing a more robust and secure operational baseline. The identified insecure commands are categorized as: • Line transport: Updates to secure remote access methods. • Device server configuration: Hardening of server-side settings. • File transfer protocols: Transitioning to encrypted transfer methods. • SNMP: Enhancements to secure management traffic. • Passwords: Strengthening authentication and credential management. • Miscellaneous: General security improvements for various system functions. The show system insecure configuration command introduced in Cisco IOS XE 17.18.2 release lists all insecure commands configured on the device. For all detected insecure configurations during device boot or upgrade, error messages are displayed. In Cisco IOS XE 26.1.1 release, all insecure CLI commands are blocked by default to strengthen your network infrastructure. If your environment requires the use of a legacy command, you must enable the system mode insecure command in global configuration mode. • Recommendation: Do not use insecure mode. This mode is temporary and will be removed in a future release. Identify and replace all insecure commands with their secure alternatives. • Upgrade behavior: If you upgrade to Cisco IOS XE 26.1.1 release with insecure commands already present in the running configuration, the system mode insecure command is automatically added to your configuration to prevent service disruption. For more information, see Resilient Infrastructure IOS XE Security Warnings Reference.

© 2026 Cisco and/or its affiliates. All rights reserved.

Product Impact	Feature	Description
Operational efficiency	UTD Support on IR8140	You can now leverage Unified Threat Defense (UTD), Cisco's premier network security solution, to access a comprehensive suite of security features—including Enterprise Firewall, IPS/IDS, Advanced Malware Protection, URL Filtering, and DNS Security—for enhanced protection across your network. For more information, see Cisco Catalyst IR8140 Heavy Duty Series Router Software Configuration Guide Supported device: IR8140
Better visibility	Device Sensor on IR8340	You can now use the device sensor network feature to gather raw endpoint data from network devices using protocols such as Cisco Discovery Protocol (CDP), Link Layer Discovery Protocol (LLDP), Dynamic Host Configuration Protocol (DHCP), DHCP version 6, and multicast DNS (mDNS). For more information, see Cisco Catalyst IR8340 Rugged Series Router Software Configuration Guide, Cisco IOS XE Release 26.1.x Supported device: IR8340
Software Reliability	Segment Routing over IPv6	SRv6 is now supported on the IR1101 router. For more information, see Cisco Catalyst IR1101 Rugged Series Router Software Configuration Guide Supported device: IR1101
Enhanced security and flexibility	CoA Support on IR1800	Change of Authorization (CoA) is now supported on the IR1800. CoA allows a RADIUS server to modify attributes for active AAA sessions after authentication. For more information, see Cisco Catalyst IR1800 Rugged Series Router Software Configuration Guide Supported device: IR1800
Greater Control	Send a UID to Identify the Unique Source When Sending GPS Coordinates Data	You can now configure Cisco routers to send a Unique Identifier (UID) when streaming NMEA GPS sentences over UDP. UID streaming is supported from both the Dead Reckoning (DR) module and cellular modems with GNSS capabilities, allowing each router to be uniquely identified by GPS data processing systems. For more information, see Cisco Catalyst IR1101 Rugged Series Router Software Configuration Guide and Cisco Catalyst IR1800 Rugged Series Router Software Configuration Guide Supported devices: IR1101 and IR1800
Upgrade	PoE+ Support on Cisco Catalyst IR8140 Router	You can use Cisco Catalyst IR8140 Heavy Duty Series Routers to provide up to 30 W of power per port to connected devices over Ethernet. For more information, see Cisco Catalyst IR8140 Heavy Duty Series Router Software Configuration Guide Supported device: IR8140
Ease of Use	Timing Support for 1588-2017 Boundary Clock on IR8340	Cisco Catalyst IR8340 Rugged Series Router now supports the IEEE 1588-2017 Power Profile in boundary clock mode. For more information, see Cisco Catalyst IR8340 Rugged Series Router Software Configuration Guide, Cisco IOS XE Release 26.1.x

© 2026 Cisco and/or its affiliates. All rights reserved.

Product Impact	Feature	Description
		Supported device: IR8340
Greater Control	Support for 20K router instances	This release introduces updated computing resource recommendations for Cisco Catalyst SD-WAN Control components. These specifications are designed to support Industrial IoT deployments of up to 20,000 devices, ensuring stability, high availability, and optimal performance across the control plane. For more information, see Cisco Catalyst IR1101 Rugged Series Router Software Configuration Guide.

New hardware features

This section provides a brief description of the new hardware features introduced in this release.

IOS XE 26.1.2

Table 2. New software features for Cisco Catalyst Rugged Series Routers, IOS XE 26.1.2

Product Impact	Feature	Description
Ease of Use	Support for P-5GS6-RC-GL PIM	P-5GS6-RC-GL PIM is now supported on the IR1101 router. For more information, see Cisco Catalyst IR1101 Rugged Series Router Software Configuration Guide Supported device: IR1101

IOS XE 26.1.1

There are no hardware features in this release.

Change in behavior

IOS XE 26.1.2

There is no change in behavior in this release.

IOS XE 26.1.1

Syslog Warning on Reload for SSH Hostkeys

After a device reload, you may see a syslog warning indicating insufficient SSH host key length, even if a strong RSA or EC key is configured.

Note:

- In the syslog warning message "**crypto key generate rsa modulus** *<modulus-size>* **label** *<label-name>",* the *<modulus-size>* and *<label-name>* represent the actual modulus size and label configured on the device.
- The SSH keypair association configuration is done using the command: **ip ssh ec|rsa** *<keypair-name>,* where *<keypair-name>* corresponds to the keypair name configured on the device.

© 2026 Cisco and/or its affiliates. All rights reserved.

Example:

RSA

Warning Observed: INSECURE DYNAMIC WARNING - Module: SSH.

Command: **crypto key generate rsa modulus** *<modulus-size>* **label** *<label-name>.*

Reason: An SSH host key has been provisioned on the device with insufficient key length.

Remediation: Please provision an SSH RSA host key with minimum modulus size of 3072 bits for enhanced security.

Sub mode: exec.

Parent CLI: Not Applicable.

EC

Warning Observed: INSECURE DYNAMIC WARNING - Module: SSH.

Command: **crypto key generate ec keysize** *<modulus-size>* **label** *<label-name>.*

Reason: An SSH host key has been provisioned on the device with insufficient key length.

Remediation: Please provision an SSH EC host key with minimum modulus size of 256 bits for enhanced security.

Sub mode: exec.

Parent CLI: Not Applicable.

If you have already configured a strong key, you can ignore the warnings that may appear during boot before the keypair association takes effect. The system applies the SSH keypair association (**ip ssh ec/rsa** *<keypair-name>*) after the boot process.

Once this configuration is active, SSH will use the correct key for secure connections.

Resolved issues

You can also access the resolved caveats for this release through the Cisco Bug Search Tool.

Note:

- This software release may contain bug fixes first introduced in other releases. To see additional information, click the bug ID to access the Cisco Bug Search Tool.
- To search for a documented Cisco product issue, enter the bug ID in the Cisco Bug Search Tool.

This table lists the resolved issues in this specific software release.

IOS XE 26.1.2

Table 3. Resolved issues for Cisco Catalyst Rugged Series Routers, IOS XE 26.1.2

Bug ID	Description
CSCws62413	IR8340 Unexpected Reload with LocalSoftADR and Kernel Panic with SMP NOPTI

© 2026 Cisco and/or its affiliates. All rights reserved.

Bug ID	Description
CSCwu34243	%TDLDB-3-DBPERSIST_OPERATION_FAILURE on DB: /tmp/rp/tdldb/0/CTRL_MNG_CFG_DB and unable to save config or reload router

IOS XE 26.1.1

Table 4. Resolved issues for Cisco Catalyst Rugged Series Routers, IOS XE 26.1.1

Bug ID	Description
CSCwq60670	NVRAM Header Corruption on Power Cycle
CSCws66114	IR8340 is failing upgrade from 17.15.1a to 17.15.4 using install commands
CSCwn98622	Hardware removal & insertion SNMP traps received after soft reload-Misleading router actual activity
CSCwo91346	IR1101 WANMON failing to reach level 2 recovery
CSCwo73978	Disappearance of band selection configuration from cellular controller after a router reload
CSCwp90680	IR1101 not completing ARP for Emerson FB-3000.
CSCwm92704	IR8340 & IE9320 redbox forwarding multiple primary announce messages to SAN
CSCwp00808	IRM-NIM-RS232 module Serial interface stops transmitting TCP raw socket traffic
CSCwp15793	TOD not synced after hard power cycle
CSCwp13058	Unintended BBU fw upgrade when miscommunication occurs between IOS and BB fw
CSCwt01182	IR8340: PTP from UTC to TAI on an IR8340 is not working
CSCwo31561	“Error in showing license Information" when " show license rum id all" is executed

Open issues

You can also access the open caveats for this release through the Cisco Bug Search Tool.

This table lists the open issues in this specific software release.

IOS XE 26.1.2

Table 5. Open issues for Cisco Catalyst Rugged Series Routers, IOS XE 26.1.2

Bug ID	Description
CSCws49513	IR8140 wpan hardware key-info does not match mesh-security keys
CSCwt05807	Telemetry sends incorrect data when sensor's reading is negative

© 2026 Cisco and/or its affiliates. All rights reserved.

Bug ID	Description
CSCwt69103	IR8340 does not send BPDU when using EtherChannel
CSCwt78851	On IR8340 router, 9124AXI and 9124AXE APs are not negotiating required power to function optimally
CSCwu37431	IR8140: WPAN incoming packet totals incorrectly calculated

IOS XE 26.1.1

Table 6. Open issues for Cisco Catalyst Rugged Series Routers, IOS XE 26.1.1

Bug ID	Description
CSCwr98904	WIFI6 module loses configuration with IR1821 reload.
CSCwt05807	Telemetry sends incorrect data when sensor's reading is negative
CSCwt42374	IOx app can exhaust router storage via core dumps & IOx app disk reservation not enforced

Known issues

IOS XE 26.1.2

There are no known issues in this release.

IOS XE 26.1.1

There are no known issues in this release.

Compatibility

This section lists compatibility information for cellular module modem firmware and OEM/PRI versions, including the latest firmware available for each modem used by Cisco IoT routers. See the Cisco Firmware Upgrade Guide for 4G LTE and 5G Cellular Modems for upgrade instructions.

Cisco IOS XE updates do not automatically update modem firmware. You should manually check and update all modems to the latest firmware version, including any related PRI and/or OEMPRI components. Refer to the following table for the most up-to-date information.

Table 7. Cellular Module Modem Firmware

Cellular Module	Modem and Firmware version	Software download link
P-5GS6-GL	FN980 38.03.0202	https://software.cisco.com/download/home/286329300/type/
P-LTEAP18-GL IRMH-LTEAP18-GL	LM960 32.00.1x9	Generic: https://software.cisco.com/download/home/286324996/type

© 2026 Cisco and/or its affiliates. All rights reserved.

Cellular Module	Modem and Firmware version	Software download link
		North America: https://software.cisco.com/download/home/286324947/type
P-LTEA-EA IRMH-LTEA-EA	Generic and Europe: EM7455 02.39.00.00 Canada, North America ATT, North American Sprint: EM7455 02.32.11.00 North America Verizon: EM7455 02.33.03.00	Generic: https://software.cisco.com/download/home/286308426/type Europe: https://software.cisco.com/download/home/286308426/type Canada: https://software.cisco.com/download/home/286319713/type North America ATT: https://software.cisco.com/download/home/286311442/type North American Sprint: https://software.cisco.com/download/home/286311455/type North America Verizon: https://software.cisco.com/download/home/286311429/type
P-LTEA-LA IRMH-LTEA-LA	Generic: EM7430 02.38.00.00 Australia Telstra EM7430 02.33.03.00 Japan: EM7430 02.38.00.00	Generic: https://software.cisco.com/download/home/286308413/type Australia Telstra: https://software.cisco.com/download/home/286311403/type Japan: https://software.cisco.com/download/home/286311416/type
P-LTE-VZW	WP7601 02.37.0x.00	https://software.cisco.com/download/home/286322139/type
P-LTE-US	WP7603 02.37.0x.00	https://software.cisco.com/download/home/286322143/type
P-LTE-JN	WP7605 02.28.03	https://software.cisco.com/download/home/286322156/type
P-LTE-GB	WP7607 02.37.03.05	https://software.cisco.com/download/home/286322147/type
P-LTE-IN	WP7608 02.28.03	https://software.cisco.com/download/home/286322152/type

© 2026 Cisco and/or its affiliates. All rights reserved.

Cellular Module	Modem and Firmware version	Software download link
P-LTE-AU	WP7609 02.28.03	https://software.cisco.com/download/home/286323720/type
P-LTE-MNA	WP7610 02.37.03.05	https://software.cisco.com/download/home/286324942/type
P-LTEA7-NA	EM7411 01.14.24.00	https://software.cisco.com/download/home/286333933/type
P-LTEA7-EAL	EM7421 01.14.22.00	https://software.cisco.com/download/home/286333937/type
P-LTEA7-JP	EM7431 01.14.22.00	https://software.cisco.com/download/home/286333939/type
P-5GS6-R16SA-GL	EM9293 02.17.08.00	https://software.cisco.com/download/home/286334597/type
P-LTE-450	Not applicable v1.3.0	Contact Intelliport for the software download link (info@intelliport.hu)

Supported software packages

This section provides information about the release packages associated with Cisco Catalyst Rugged Series Routers.

For latest software downloads, see the Software Download page.

Note: NPE stands for No Payload Encryption.

IOS XE 26.1.2

Table 8. Software packages for Cisco Catalyst Rugged Series Routers, IOS XE 26.1.2

Router	Image type	Filename
IR1101	Universal	ir1101-universalk9.26.01.02.SPA.bin
IR1800	Universal	ir1800-universalk9.26.01.02.SPA.bin
	UTD Engine for Cisco IR1800	secapp-utd.26.01.02.1.0.3_SV3.3.5.0_XE26.1.aarch64.tar
IR8100	Universal	ir8100-universalk9.26.01.02.SPA.bin
	UTD Engine for Cisco IR8100	secapp-utd.26.01.02.1.0.1_SV3.3.5.0_XE26.1.aarch64.tar

© 2026 Cisco and/or its affiliates. All rights reserved.

Router	Image type	Filename
IR8340	Universal	ir8340-universalk9.26.01.02.SPA.bin
	UTD Engine for Cisco IR8340	secapp-utd.26.01.02.1.0.1_SV3.3.5.0_XE26.1.x86_64.tar

IOS XE 26.1.1

Table 9. Software packages for Cisco Catalyst Rugged Series Routers, IOS XE 26.1.1

Router	Image type	Filename
IR1101	Universal	ir1101-universalk9.26.01.01.SPA.bin
IR1800	Universal	ir1800-universalk9.26.01.01.SPA.bin
	UTD Engine for Cisco IR1800	secapp-utd.26.01.01.1.0.1_SV3.3.5.0_XE26.1.aarch64.tar
IR8100	Universal	ir8100-universalk9.26.01.01.SPA.bin
	UTD Engine for Cisco IR8100	secapp-utd.26.01.01.1.0.1_SV3.3.5.0_XE26.1.aarch64.tar
IR8340	Universal	ir8340-universalk9.26.01.01.SPA.bin
	UTD Engine for Cisco IR8340	secapp-utd.26.01.01.1.0.1_SV3.3.5.0_XE26.1.x86_64.tar

Port Naming Conventions

This section shows the names of the ports on Cisco Catalyst IR1101, IR1800, IR8140, and IR8340 routers.

Table 10. Cisco Catalyst IR1101 Rugged Series Router

Port	Naming Convention
Gigabit Ethernet combo port	GigabitEthernet0/0/0
Gigabit Ethernet SFP port on IRM-1100	GigabitEthernet0/0/5
Gigabit Ethernet on IRM-1100-4A2T mounted on the Expansion side	GigabitEthernet0/0/5 GigabitEthernet0/0/6
Fast Ethernet ports	FastEthernet0/0/1 FastEthernet0/0/2 FastEthernet0/0/3 FastEthernet0/0/4
Cellular Interface on IR1101 Base	Cellular 0/1/0 Cellular 0/1/1

© 2026 Cisco and/or its affiliates. All rights reserved.

Port	Naming Convention
Cellular Interface on IRM-1100 mounted on the top (EM) side	Cellular 0/3/0 Cellular 0/3/1
Cellular Interface on IRM-1100 mounted on the bottom (CM) side	Cellular 0/4/0 Cellular 0/4/1
Asynchronous Serial Interface Base	async0/2/0
IRM-1100-4A2T is mounted on the top (EM) side	async 0/3/0 async 0/3/1 async 0/3/2 async 0/3/3
IRM-1100-4A2T is mounted on the bottom (CM) side	async 0/4/0 async 0/4/1 async 0/4/2 async 0/4/3
USB	usbflash0:
mSATA	msata:
IR1101 Base Unit Alarm input	alarm contact 0
GPIO on IRM-1100	alarm contact 1-4
LoRaWAN interface on IR1101 Base	LORAWAN0/1/0
LoRaWAN interface on the top (EM) side	LORAWAN0/3/0
Gigabit Ethernet interface for LTE 450MHz module on IR1101 Base	GigabitEthernet0/1/0 GigabitEthernet0/1/0.x for multiPDN operation
Gigabit Ethernet interface for LTE 450MHz module mounted on the bottom (CM) side	GI0/4/0

Table 11. Cisco Catalyst IR1800 Rugged Series Router

Port	Naming Convention
Gigabit Ethernet combo port	GigabitEthernet0/0/0
Gigabit Ethernet ports	GigabitEthernet0/1/0 GigabitEthernet0/1/1

© 2026 Cisco and/or its affiliates. All rights reserved.

Port	Naming Convention
	GigabitEthernet0/1/2 GigabitEthernet0/1/3
Cellular Interface	Cellular 0/4/0 Cellular 0/4/1 Cellular 0/5/0 Cellular 0/5/1
Asynchronous Serial Interface	Async0/2/0 Async0/2/1 (when the base platform supports two asynchronous serial interfaces)
Wi-Fi Interface	WI0/1/4
USB	usbflash0:
mSATA	msata:
GPIO	alarm contact 1-4

Table 12. Cisco Catalyst IR8140 Heavy Duty Series Router

Port	Naming Convention
Gigabit Ethernet ports	GigabitEthernet0/0/0 GigabitEthernet0/0/1
Cellular Interface	Cellular 0/2/0 Cellular 0/2/1 Cellular 0/3/0 Cellular 0/3/1
SSD	VirtualPortGroup0
WPAN	Wpan 0/1/0 Wpan 0/2/0 Wpan 0/3/0
Digital I/O	alarm contact 1-2

Table 13. Cisco Catalyst IR8340 Rugged Series Router

© 2026 Cisco and/or its affiliates. All rights reserved.

Port	Naming Convention
Gigabit Ethernet WAN ports	GigabitEthernet0/0/0 GigabitEthernet0/0/1
Gigabit Ethernet LAN ports	GigabitEthernet0/1/0 GigabitEthernet0/1/1 GigabitEthernet0/1/2 GigabitEthernet0/1/3 GigabitEthernet0/1/4 GigabitEthernet0/1/5 GigabitEthernet0/1/6 GigabitEthernet0/1/7 GigabitEthernet0/1/8 GigabitEthernet0/1/9 GigabitEthernet0/1/10 GigabitEthernet0/1/11
Cellular Interface	Cellular 0/4/0 Cellular 0/4/1 Cellular 0/5/0 Cellular 0/5/1
NIM Interface (Asynchronous/Synchronous Serial Ports or E1/T1 ports)	0/2/0 0/2/1 0/3/0 0/3/1
mSATA SSD	msata:
GPIO	alarm contact 0-2
USB Port	usb0:
Console Port	Line console 0

Related resources

Table 14. Related resources

Document	Description
Cisco IOS XE	Provides information about products supported by Cisco IOS XE.

© 2026 Cisco and/or its affiliates. All rights reserved.

Document	Description
Cisco Catalyst IR1101 Rugged Series Router Cisco Catalyst IR1800 Rugged Series Router Cisco Catalyst IR8140 Heavy Duty Series Router Cisco Catalyst IR8340 Rugged Series Router	Provides data sheet for the specified routers.
Cisco Industrial Routers and Industrial Wireless Access Points Antenna Guide	Provides descriptions and installation instructions for wireless antennas supported on the Cisco Industrial Series Routers and Industrial Wireless Access Points.
Cisco SD-WAN	Provides information about SD-WAN releases and resources.
Cisco IoT Field Network Director	Provides information about Cisco IoT Field Network Director releases and resources.
Cisco Industrial Network Director	Provides information about Cisco Industrial Network Director releases and resources.
Smart Licensing Using Policy on the Cisco Catalyst IR1101, IR1800, IR8140, and IR8340 Routers or the Cisco Industrial IoT Licensing	Provides information about Smart Licensing Using Policy solutions and their deployment on IOS XE routers.
Cisco Support	You can submit a service request here.
Cisco TAC	Provides the most up-to-date troubleshooting information.
Cisco Feature Navigator	Use CFN to browse Cisco products and find relevant features and licenses. It allows you to compare platforms, determine common features between products, and identify unique product features. Cisco Feature Navigator also includes a MIB Locator tab.

© 2026 Cisco and/or its affiliates. All rights reserved.

Legal information

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: https://www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

© 2026 Cisco Systems, Inc. All rights reserved.