

# Intersight FI Infrastructure Software Bundle


- FI Infrastructure Firmware Bundle for Cisco UCS 6600, 6500, and 6400 Series 6.0(2.260067) and Cisco UCS X-Series Direct 6.0(2.260067), on page 1
- FI Infrastructure Firmware Bundle for Cisco UCS 6600, 6500, and 6400 Series 6.0(2.260055) and Cisco UCS X-Series Direct 6.0(2.260055), on page 3
- FI Infrastructure Firmware Bundle for Cisco UCS 6600, 6500, and 6400 Series 6.0(1.260006) and Cisco UCS X-Series Direct 6.0(1.260006), on page 5
- FI Infrastructure Firmware Bundle for Cisco UCS 6600, 6500, and 6400 Series 6.0(2.260045) and Cisco UCS X-Series Direct 6.0(2.260045), on page 6
- FI Infrastructure Firmware Bundle for Cisco UCS 6600, 6500, and 6400 Series 6.0(1.260003) and Cisco UCS X-Series Direct 6.0(1.260003), on page 8
- FI Infrastructure Firmware Bundle for Cisco UCS 6600, 6500, and 6400 Series 6.0(1.250243) and Cisco UCS X-Series Direct 6.0(1.250243), on page 10
- FI Infrastructure Firmware Bundle for Cisco UCS 6600, 6500, and 6400 Series 6.0(1.250229) and Cisco UCS X-Series Direct 6.0(1.250229), on page 12
- FI Infrastructure Firmware Bundle for Cisco UCS 6600, 6500, and 6400 Series 6.0(1.250198) and Cisco UCS X-Series Direct 6.0(1.250198), on page 13
- Deprecated Hardware, on page 15


## FI Infrastructure Firmware Bundle for Cisco UCS 6600, 6500, and 6400 Series 6.0(2.260067) and Cisco UCS X-Series Direct 6.0(2.260067)

IMM infrastructure firmware bundle contains the following images for Cisco UCS 6600 Series FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-FI-6664 | 10.5(1)I60(2d) | ucsfi.10.5.1.I60.2d.F.bin |
| UCS-FI-6652 | 10.5(1)I60(2d) | ucsfi.10.5.1.I60.2d.F.bin |
| UCS-IOM-2304 | 4.0(4.22) | NA |
| UCS-IOM-2304V2 | 4.0(4.22) | NA |

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-IOM-2408 | 6.0(2d) | chassis4.img |
| UCSBX-I-9108-25G | 6.0(2d) | chassis5.img |
| UCSX-I-9108-25G | 6.0(2d) | chassis5.img |
| UCSX-I-9108-100G | 6.0(2d) | chassis5.img |
| UCSB-PSU-2500ACDV-ECD15020029 | 03.00.00 | cmc-psuDV-Delta.03.00.00.bin |
| UCSB-PSU-2500ACDV-AA26870L-A | 05.0b | cmc-psuDV-Emerson.05.0b.bin |

IMM infrastructure firmware bundle contains the following images for Cisco UCS 6500 Series FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-FI-6536 | 10.5(1)I60(2d) | ucsfi.10.5.1.I60.2d.F.bin |
| UCS-IOM-2204XP | 4.0(4.22) | NA |
| UCS-IOM-2208XP | 4.0(4.22) | NA |
| UCS-IOM-2304 | 4.0(4.22) | NA |
| UCS-IOM-2304V2 | 4.0(4.22) | NA |
| UCS-IOM-2408 | 6.0(2d) | chassis4.img |
| UCSBX-I-9108-25G | 6.0(2d) | chassis5.img |
| UCSX-I-9108-25G | 6.0(2d) | chassis5.img |
| UCSX-I-9108-100G | 6.0(2d) | chassis5.img |
| UCSB-PSU-2500ACDV-ECD15020029 | 03.00.00 | cmc-psuDV-Delta.03.00.00.bin |
| UCSB-PSU-2500ACDV-AA26870L-A | 05.0b | cmc-psuDV-Emerson.05.0b.bin |

IMM infrastructure firmware bundle contains the following images for Cisco UCS 6400 Series FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-FI-6454 | 10.5(1)I60(2d) | ucsfi.10.5.1.I60.2d.F.bin |
| UCS-FI-64108 | 10.5(1)I60(2d) | ucsfi.10.5.1.I60.2d.F.bin |
| UCS-IOM-2204XP | 4.0(4.22) | NA |
| UCS-IOM-2208XP | 4.0(4.22) | NA |
| UCS-IOM-2408 | 6.0(2d) | chassis4.img |
| UCSBX-I-9108-25G | 6.0(2d) | chassis5.img |

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCSX-I-9108-25G | 6.0(2d) | chassis5.img |
| UCSB-PSU-2500ACDV-ECD15020029 | 03.00.00 | cmc-psuDV-Delta.03.00.00.bin |
| UCSB-PSU-2500ACDV-AA26870L-A | 05.0b | cmc-psuDV-Emerson.05.0b.bin |

IMM infrastructure firmware bundle contains the following images for Cisco UCS X-Series Direct FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCSX-S9108-100G | 10.5(1)I60(2d) | ucsfi.10.5.1.I60.2d.F.bin |
| UCSX-S9108-100G | 6.0(2d) | ucs-manager-k9.6.0.2d.bin |
| UCSBX-I-9108-25G | 6.0(2d) | chassis5.img |
| UCSX-I-9108-25G | 6.0(2d) | chassis5.img |
| UCSX-I-9108-100G | 6.0(2d) | chassis5.img |

# FI Infrastructure Firmware Bundle for Cisco UCS 6600, 6500, and 6400 Series 6.0(2.260055) and Cisco UCS X-Series Direct 6.0(2.260055)

IMM infrastructure firmware bundle contains the following images for Cisco UCS 6600 Series FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-FI-6664 | 10.5(1)I60(2c) | ucsfi.10.5.1.I60.2c.F.bin |
| UCS-FI-6652 | 10.5(1)I60(2c) | ucsfi.10.5.1.I60.2c.F.bin |
| UCS-IOM-2304 | 4.0(4.22) | NA |
| UCS-IOM-2304V2 | 4.0(4.22) | NA |
| UCS-IOM-2408 | 6.0(2c) | chassis4.img |
| UCSBX-I-9108-25G | 6.0(2c) | chassis5.img |
| UCSX-I-9108-25G | 6.0(2c) | chassis5.img |
| UCSX-I-9108-100G | 6.0(2c) | chassis5.img |
| UCSB-PSU-2500ACDV-ECD15020029 | 03.00.00 | cmc-psuDV-Delta.03.00.00.bin |
| UCSB-PSU-2500ACDV-AA26870L-A | 05.0b | cmc-psuDV-Emerson.05.0b.bin |

IMM infrastructure firmware bundle contains the following images for Cisco UCS 6500 Series FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-FI-6536 | 10.5(1)I60(2c) | ucsfi.10.5.1.I60.2c.F.bin |
| UCS-IOM-2204XP | 4.0(4.22) | NA |
| UCS-IOM-2208XP | 4.0(4.22) | NA |
| UCS-IOM-2304 | 4.0(4.22) | NA |
| UCS-IOM-2304V2 | 4.0(4.22) | NA |
| UCS-IOM-2408 | 6.0(2c) | chassis4.img |
| UCSBX-I-9108-25G | 6.0(2c) | chassis5.img |
| UCSX-I-9108-25G | 6.0(2c) | chassis5.img |
| UCSX-I-9108-100G | 6.0(2c) | chassis5.img |
| UCSB-PSU-2500ACDV-ECD15020029 | 03.00.00 | cmc-psuDV-Delta.03.00.00.bin |
| UCSB-PSU-2500ACDV-AA26870L-A | 05.0b | cmc-psuDV-Emerson.05.0b.bin |

IMM infrastructure firmware bundle contains the following images for Cisco UCS 6400 Series FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-FI-6454 | 10.5(1)I60(2c) | ucsfi.10.5.1.I60.2c.F.bin |
| UCS-FI-64108 | 10.5(1)I60(2c) | ucsfi.10.5.1.I60.2c.F.bin |
| UCS-IOM-2204XP | 4.0(4.22) | NA |
| UCS-IOM-2208XP | 4.0(4.22) | NA |
| UCS-IOM-2408 | 6.0(2c) | chassis4.img |
| UCSBX-I-9108-25G | 6.0(2c) | chassis5.img |
| UCSX-I-9108-25G | 6.0(2c) | chassis5.img |
| UCSB-PSU-2500ACDV-ECD15020029 | 03.00.00 | cmc-psuDV-Delta.03.00.00.bin |
| UCSB-PSU-2500ACDV-AA26870L-A | 05.0b | cmc-psuDV-Emerson.05.0b.bin |

IMM infrastructure firmware bundle contains the following images for Cisco UCS X-Series Direct FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCSX-S9108-100G | 10.5(1)I60(2c) | ucsfi.10.5.1.I60.2c.F.bin |
| UCSX-S9108-100G | 6.0(2c) | ucs-manager-k9.6.0.2c.bin |
| UCSBX-I-9108-25G | 6.0(2c) | chassis5.img |

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCSX-I-9108-25G | 6.0(2c) | chassis5.img |
| UCSX-I-9108-100G | 6.0(2c) | chassis5.img |

# FI Infrastructure Firmware Bundle for Cisco UCS 6600, 6500, and 6400 Series 6.0(1.260006) and Cisco UCS X-Series Direct 6.0(1.260006)

IMM infrastructure firmware bundle contains the following images for Cisco UCS 6600 Series FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-FI-6664 | 10.5(1)I60(1f) | ucsfi.10.5.1.I60.1f.F.bin |
| UCS-FI-6652 | 10.5(1)I60(1f) | ucsfi.10.5.1.I60.1f.F.bin |
| UCS-IOM-2304 | 4.3(6c) | chassis3.img |
| UCS-IOM-2304V2 | 4.3(6c) | chassis3.img |
| UCS-IOM-2408 | 6.0(1f) | chassis4.img |
| UCSBX-I-9108-25G | 6.0(1f) | chassis5.img |
| UCSX-I-9108-25G | 6.0(1f) | chassis5.img |
| UCSX-I-9108-100G | 6.0(1f) | chassis5.img |
| UCSB-PSU-2500ACDV-ECD15020029 | 03.00.00 | cmc-psuDV-Delta.03.00.00.bin |
| UCSB-PSU-2500ACDV-AA26870L-A | 05.0b | cmc-psuDV-Emerson.05.0b.bin |

IMM infrastructure firmware bundle contains the following images for Cisco UCS 6500 Series FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-FI-6536 | 10.5(1)I60(1f) | ucsfi.10.5.1.I60.1f.F.bin |
| UCS-IOM-2204XP | 4.3(6c) | chassis_soquel.img |
| UCS-IOM-2208XP | 4.3(6c) | chassis_soquel.img |
| UCS-IOM-2304 | 4.3(6c) | chassis3.img |
| UCS-IOM-2304V2 | 4.3(6c) | chassis3.img |
| UCS-IOM-2408 | 6.0(1f) | chassis4.img |
| UCSBX-I-9108-25G | 6.0(1f) | chassis5.img |

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCSX-I-9108-25G | 6.0(1f) | chassis5.img |
| UCSX-I-9108-100G | 6.0(1f) | chassis5.img |
| UCSB-PSU-2500ACDV-ECD15020029 | 03.00.00 | cmc-psuDV-Delta.03.00.00.bin |
| UCSB-PSU-2500ACDV-AA26870L-A | 05.0b | cmc-psuDV-Emerson.05.0b.bin |

IMM infrastructure firmware bundle contains the following images for Cisco UCS 6400 Series FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-FI-6454 | 10.5(1)I60(1f) | ucsfi.10.5.1.I60.1f.F.bin |
| UCS-FI-64108 | 10.5(1)I60(1f) | ucsfi.10.5.1.I60.1f.F.bin |
| UCS-IOM-2204XP | 4.3(6c) | chassis_soquel.img |
| UCS-IOM-2208XP | 4.3(6c) | chassis_soquel.img |
| UCS-IOM-2408 | 6.0(1f) | chassis4.img |
| UCSBX-I-9108-25G | 6.0(1f) | chassis5.img |
| UCSX-I-9108-25G | 6.0(1f) | chassis5.img |
| UCSB-PSU-2500ACDV-ECD15020029 | 03.00.00 | cmc-psuDV-Delta.03.00.00.bin |
| UCSB-PSU-2500ACDV-AA26870L-A | 05.0b | cmc-psuDV-Emerson.05.0b.bin |

IMM infrastructure firmware bundle contains the following images for Cisco UCS X-Series Direct FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCSX-S9108-100G | 10.5(1)I60(1f) | ucsfi.10.5.1.I60.1f.F.bin |
| UCSX-S9108-100G | 6.0(1h) | ucs-manager-k9.6.0.1h.bin |
| UCSBX-I-9108-25G | 6.0(1f) | chassis5.img |
| UCSX-I-9108-25G | 6.0(1f) | chassis5.img |
| UCSX-I-9108-100G | 6.0(1f) | chassis5.img |

# FI Infrastructure Firmware Bundle for Cisco UCS 6600, 6500, and 6400 Series 6.0(2.260045) and Cisco UCS X-Series Direct 6.0(2.260045)

IMM infrastructure firmware bundle contains the following images for Cisco UCS 6600 Series FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-FI-6664 | 10.5(1)I60(2a) | ucsfi.10.5.1.I60.2a.F.bin |
| UCS-FI-6652 | 10.5(1)I60(2a) | ucsfi.10.5.1.I60.2a.F.bin |
| UCS-IOM-2304 | 4.0(4.22) | N/A |
| UCS-IOM-2304V2 | 4.0(4.22) | N/A |
| UCS-IOM-2408 | 6.0(2a) | chassis4.img |
| UCSBX-I-9108-25G | 6.0(2a) | chassis5.img |
| UCSX-I-9108-25G | 6.0(2a) | chassis5.img |
| UCSX-I-9108-100G | 6.0(2a) | chassis5.img |
| UCSB-PSU-2500ACDV-ECD15020029 | 03.00.00 | cmc-psuDV-Delta.03.00.00.bin |
| UCSB-PSU-2500ACDV-AA26870L-A | 05.0b | cmc-psuDV-Emerson.05.0b.bin |

IMM infrastructure firmware bundle contains the following images for Cisco UCS 6500 Series FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-FI-6536 | 10.5(1)I60(2a) | ucsfi.10.5.1.I60.2a.F.bin |
| UCS-IOM-2204XP | 4.0(4.22) | N/A |
| UCS-IOM-2208XP | 4.0(4.22) | N/A |
| UCS-IOM-2304 | 4.0(4.22) | N/A |
| UCS-IOM-2304V2 | 4.0(4.22) | N/A |
| UCS-IOM-2408 | 6.0(2a) | chassis4.img |
| UCSBX-I-9108-25G | 6.0(2a) | chassis5.img |
| UCSX-I-9108-25G | 6.0(2a) | chassis5.img |
| UCSX-I-9108-100G | 6.0(2a) | chassis5.img |
| UCSB-PSU-2500ACDV-ECD15020029 | 03.00.00 | cmc-psuDV-Delta.03.00.00.bin |
| UCSB-PSU-2500ACDV-AA26870L-A | 05.0b | cmc-psuDV-Emerson.05.0b.bin |

IMM infrastructure firmware bundle contains the following images for Cisco UCS 6400 Series FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-FI-6454 | 10.5(1)I60(2a) | ucsfi.10.5.1.I60.2a.F.bin |
| UCS-FI-64108 | 10.5(1)I60(2a) | ucsfi.10.5.1.I60.2a.F.bin |

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-IOM-2204XP | 4.0(4.22) | N/A |
| UCS-IOM-2208XP | 4.0(4.22) | N/A |
| UCS-IOM-2408 | 6.0(2a) | chassis4.img |
| UCSBX-I-9108-25G | 6.0(2a) | chassis5.img |
| UCSX-I-9108-25G | 6.0(2a) | chassis5.img |
| UCSB-PSU-2500ACDV-ECD15020029 | 03.00.00 | cmc-psuDV-Delta.03.00.00.bin |
| UCSB-PSU-2500ACDV-AA26870L-A | 05.0b | cmc-psuDV-Emerson.05.0b.bin |

IMM infrastructure firmware bundle contains the following images for Cisco UCS X-Series Direct FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCSX-S9108-100G | 10.5(1)I60(2b) | ucsfi.10.5.1.I60.2b.F.bin |
| UCSX-S9108-100G | 6.0(2b) | ucs-manager-k9.6.0.2b.bin |
| UCSBX-I-9108-25G | 6.0(2b) | chassis5.img |
| UCSX-I-9108-25G | 6.0(2b) | chassis5.img |
| UCSX-I-9108-100G | 6.0(2b) | chassis5.img |

# FI Infrastructure Firmware Bundle for Cisco UCS 6600, 6500, and 6400 Series 6.0(1.260003) and Cisco UCS X-Series Direct 6.0(1.260003)

IMM infrastructure firmware bundle contains the following images for Cisco UCS 6600 Series FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-FI-6664 | 10.5(1)I60(1e) | ucsfi.10.5.1.I60.1e.F.bin |
| UCS-FI-6652 | 10.5(1)I60(1e) | ucsfi.10.5.1.I60.1e.F.bin |
| UCS-IOM-2304 | 4.3(6c) | chassis3.img |
| UCS-IOM-2304V2 | 4.3(6c) | chassis3.img |
| UCS-IOM-2408 | 6.0(1e) | chassis4.img |
| UCSBX-I-9108-25G | 6.0(1e) | chassis5.img |
| UCSX-I-9108-25G | 6.0(1e) | chassis5.img |

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCSX-I-9108-100G | 6.0(1e) | chassis5.img |
| UCSB-PSU-2500ACDV-ECD15020029 | 03.00.00 | cmc-psuDV-Delta.03.00.00.bin |
| UCSB-PSU-2500ACDV-AA26870L-A | 05.0b | cmc-psuDV-Emerson.05.0b.bin |

IMM infrastructure firmware bundle contains the following images for Cisco UCS 6500 Series FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-FI-6536 | 10.5(1)I60(1e) | ucsfi.10.5.1.I60.1e.F.bin |
| UCS-IOM-2204XP | 4.3(6c) | chassis_soquel.img |
| UCS-IOM-2208XP | 4.3(6c) | chassis_soquel.img |
| UCS-IOM-2304 | 4.3(6c) | chassis3.img |
| UCS-IOM-2304V2 | 4.3(6c) | chassis3.img |
| UCS-IOM-2408 | 6.0(1e) | chassis4.img |
| UCSBX-I-9108-25G | 6.0(1e) | chassis5.img |
| UCSX-I-9108-25G | 6.0(1e) | chassis5.img |
| UCSX-I-9108-100G | 6.0(1e) | chassis5.img |
| UCSB-PSU-2500ACDV-ECD15020029 | 03.00.00 | cmc-psuDV-Delta.03.00.00.bin |
| UCSB-PSU-2500ACDV-AA26870L-A | 05.0b | cmc-psuDV-Emerson.05.0b.bin |

IMM infrastructure firmware bundle contains the following images for Cisco UCS 6400 Series FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-FI-6454 | 10.5(1)I60(1e) | ucsfi.10.5.1.I60.1e.F.bin |
| UCS-FI-64108 | 10.5(1)I60(1e) | ucsfi.10.5.1.I60.1e.F.bin |
| UCS-IOM-2204XP | 4.3(6c) | chassis_soquel.img |
| UCS-IOM-2208XP | 4.3(6c) | chassis_soquel.img |
| UCS-IOM-2408 | 6.0(1e) | chassis4.img |
| UCSBX-I-9108-25G | 6.0(1e) | chassis5.img |
| UCSX-I-9108-25G | 6.0(1e) | chassis5.img |
| UCSB-PSU-2500ACDV-ECD15020029 | 03.00.00 | cmc-psuDV-Delta.03.00.00.bin |
| UCSB-PSU-2500ACDV-AA26870L-A | 05.0b | cmc-psuDV-Emerson.05.0b.bin |

IMM infrastructure firmware bundle contains the following images for Cisco UCS X-Series Direct FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCSX-S9108-100G | 10.5(1)I60(1e) | ucsfi.10.5.1.I60.1e.F.bin |
| UCSX-S9108-100G | 6.0(1f) | ucs-manager-k9.6.0.1f.bin |
| UCSBX-I-9108-25G | 6.0(1e) | chassis5.img |
| UCSX-I-9108-25G | 6.0(1e) | chassis5.img |
| UCSX-I-9108-100G | 6.0(1e) | chassis5.img |

# FI Infrastructure Firmware Bundle for Cisco UCS 6600, 6500, and 6400 Series 6.0(1.250243) and Cisco UCS X-Series Direct 6.0(1.250243)

IMM infrastructure firmware bundle contains the following images for Cisco UCS 6600 Series FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-FI-6664 | 10.5(1)I60(1d) | ucsfi.10.5.1.I60.1d.F.bin |
| UCS-FI-6652 | 10.5(1)I60(1d) | ucsfi.10.5.1.I60.1d.F.bin |
| UCS-IOM-2304 | 4.3(6c) | chassis3.img |
| UCS-IOM-2304V2 | 4.3(6c) | chassis3.img |
| UCS-IOM-2408 | 6.0(1d) | chassis4.img |
| UCSBX-I-9108-25G | 6.0(1d) | chassis5.img |
| UCSX-I-9108-25G | 6.0(1d) | chassis5.img |
| UCSX-I-9108-100G | 6.0(1d) | chassis5.img |
| UCSB-PSU-2500ACDV-ECD15020029 | 03.00.00 | cmc-psuDV-Delta.03.00.00.bin |
| UCSB-PSU-2500ACDV-AA26870L-A | 05.0b | cmc-psuDV-Emerson.05.0b.bin |

IMM infrastructure firmware bundle contains the following images for Cisco UCS 6500 Series FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-FI-6536 | 10.5(1)I60(1d) | ucsfi.10.5.1.I60.1d.F.bin |
| UCS-IOM-2204XP | 4.3(6c) | chassis_soquel.img |
| UCS-IOM-2208XP | 4.3(6c) | chassis_soquel.img |

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-IOM-2304 | 4.3(6c) | chassis3.img |
| UCS-IOM-2304V2 | 4.3(6c) | chassis3.img |
| UCS-IOM-2408 | 6.0(1d) | chassis4.img |
| UCSBX-I-9108-25G | 6.0(1d) | chassis5.img |
| UCSX-I-9108-25G | 6.0(1d) | chassis5.img |
| UCSX-I-9108-100G | 6.0(1d) | chassis5.img |
| UCSB-PSU-2500ACDV-ECD15020029 | 03.00.00 | cmc-psuDV-Delta.03.00.00.bin |
| UCSB-PSU-2500ACDV-AA26870L-A | 05.0b | cmc-psuDV-Emerson.05.0b.bin |

IMM infrastructure firmware bundle contains the following images for Cisco UCS 6400 Series FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-FI-6454 | 10.5(1)I60(1d) | ucsfi.10.5.1.I60.1d.F.bin |
| UCS-FI-64108 | 10.5(1)I60(1d) | ucsfi.10.5.1.I60.1d.F.bin |
| UCS-IOM-2204XP | 4.3(6c) | chassis_soquel.img |
| UCS-IOM-2208XP | 4.3(6c) | chassis_soquel.img |
| UCS-IOM-2408 | 6.0(1d) | chassis4.img |
| UCSBX-I-9108-25G | 6.0(1d) | chassis5.img |
| UCSX-I-9108-25G | 6.0(1d) | chassis5.img |
| UCSB-PSU-2500ACDV-ECD15020029 | 03.00.00 | cmc-psuDV-Delta.03.00.00.bin |
| UCSB-PSU-2500ACDV-AA26870L-A | 05.0b | cmc-psuDV-Emerson.05.0b.bin |

IMM infrastructure firmware bundle contains the following images for Cisco UCS X-Series Direct FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCSX-S9108-100G | 10.5(1)I60(1d) | ucsfi.10.5.1.I60.1d.F.bin |
| UCSX-S9108-100G | 6.0(1e) | ucs-manager-k9.6.0.1e.bin |
| UCSBX-I-9108-25G | 6.0(1d) | chassis5.img |
| UCSX-I-9108-25G | 6.0(1d) | chassis5.img |
| UCSX-I-9108-100G | 6.0(1d) | chassis5.img |

# FI Infrastructure Firmware Bundle for Cisco UCS 6600, 6500, and 6400 Series 6.0(1.250229) and Cisco UCS X-Series Direct 6.0(1.250229)

IMM infrastructure firmware bundle contains the following images for Cisco UCS 6600 Series FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-FI-6664 | 10.5(1)I60(1c) | ucsfi.10.5.1.I60.1c.F.bin |
| UCS-FI-6652 | 10.5(1)I60(1c) | ucsfi.10.5.1.I60.1c.F.bin |
| UCS-IOM-2304 | 4.3(6c) | chassis3.img |
| UCS-IOM-2304V2 | 4.3(6c) | chassis3.img |
| UCS-IOM-2408 | 6.0(1c) | chassis4.img |
| UCSBX-I-9108-25G | 6.0(1c) | chassis5.img |
| UCSX-I-9108-25G | 6.0(1c) | chassis5.img |
| UCSX-I-9108-100G | 6.0(1c) | chassis5.img |
| UCSB-PSU-2500ACDV-ECD15020029 | 03.00.00 | cmc-psuDV-Delta.03.00.00.bin |
| UCSB-PSU-2500ACDV-AA26870L-A | 05.0b | cmc-psuDV-Emerson.05.0b.bin |

IMM infrastructure firmware bundle contains the following images for Cisco UCS 6500 Series FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-FI-6536 | 10.5(1)I60(1c) | ucsfi.10.5.1.I60.1c.F.bin |
| UCS-IOM-2204XP | 4.3(6c) | chassis_soquel.img |
| UCS-IOM-2208XP | 4.3(6c) | chassis_soquel.img |
| UCS-IOM-2304 | 4.3(6c) | chassis3.img |
| UCS-IOM-2304V2 | 4.3(6c) | chassis3.img |
| UCS-IOM-2408 | 6.0(1c) | chassis4.img |
| UCSBX-I-9108-25G | 6.0(1c) | chassis5.img |
| UCSX-I-9108-25G | 6.0(1c) | chassis5.img |
| UCSX-I-9108-100G | 6.0(1c) | chassis5.img |
| UCSB-PSU-2500ACDV-ECD15020029 | 03.00.00 | cmc-psuDV-Delta.03.00.00.bin |

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCSB-PSU-2500ACDV-AA26870L-A | 05.0b | cmc-psuDV-Emerson.05.0b.bin |

IMM infrastructure firmware bundle contains the following images for Cisco UCS 6400 Series FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-FI-6454 | 10.5(1)I60(1c) | ucsfi.10.5.1.I60.1c.F.bin |
| UCS-FI-64108 | 10.5(1)I60(1c) | ucsfi.10.5.1.I60.1c.F.bin |
| UCS-IOM-2204XP | 4.3(6c) | chassis_soquel.img |
| UCS-IOM-2208XP | 4.3(6c) | chassis_soquel.img |
| UCS-IOM-2408 | 6.0(1c) | chassis4.img |
| UCSBX-I-9108-25G | 6.0(1c) | chassis5.img |
| UCSX-I-9108-25G | 6.0(1c) | chassis5.img |
| UCSB-PSU-2500ACDV-ECD15020029 | 03.00.00 | cmc-psuDV-Delta.03.00.00.bin |
| UCSB-PSU-2500ACDV-AA26870L-A | 05.0b | cmc-psuDV-Emerson.05.0b.bin |

IMM infrastructure firmware bundle contains the following images for Cisco UCS X-Series Direct FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCSX-S9108-100G | 10.5(1)I60(1c) | ucsfi.10.5.1.I60.1c.F.bin |
| UCSX-S9108-100G | 6.0(1d) | ucs-manager-k9.6.0.1d.bin |
| UCSBX-I-9108-25G | 6.0(1c) | chassis5.img |
| UCSX-I-9108-25G | 6.0(1c) | chassis5.img |
| UCSX-I-9108-100G | 6.0(1c) | chassis5.img |

# FI Infrastructure Firmware Bundle for Cisco UCS 6600, 6500, and 6400 Series 6.0(1.250198) and Cisco UCS X-Series Direct 6.0(1.250198)

IMM infrastructure firmware bundle contains the following images for Cisco UCS 6600 Series FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-FI-6664 | 10.5(1)I60(1a) | ucsfi.10.5.1.I60.1a.F.bin |
| UCS-IOM-2304 | 4.3(6b) | chassis3.img |

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-IOM-2304V2 | 4.3(6b) | chassis3.img |
| UCS-IOM-2408 | 6.0(1a) | chassis4.img |
| UCSBX-I-9108-25G | 6.0(1a) | chassis5.img |
| UCSX-I-9108-25G | 6.0(1a) | chassis5.img |
| UCSX-I-9108-100G | 6.0(1a) | chassis5.img |
| UCSB-PSU-2500ACDV-ECD15020029 | 03.00.00 | cmc-psuDV-Delta.03.00.00.bin |
| UCSB-PSU-2500ACDV-AA26870L-A | 05.0b | cmc-psuDV-Emerson.05.0b.bin |

IMM infrastructure firmware bundle contains the following images for Cisco UCS 6500 Series FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-FI-6536 | 10.5(1)I60(1a) | ucsfi.10.5.1.I60.1a.F.bin |
| UCS-IOM-2204XP | 4.3(6b) | chassis_soquel.img |
| UCS-IOM-2208XP | 4.3(6b) | chassis_soquel.img |
| UCS-IOM-2304 | 4.3(6b) | chassis3.img |
| UCS-IOM-2304V2 | 4.3(6b) | chassis3.img |
| UCS-IOM-2408 | 6.0(1a) | chassis4.img |
| UCSBX-I-9108-25G | 6.0(1a) | chassis5.img |
| UCSX-I-9108-25G | 6.0(1a) | chassis5.img |
| UCSX-I-9108-100G | 6.0(1a) | chassis5.img |
| UCSB-PSU-2500ACDV-ECD15020029 | 03.00.00 | cmc-psuDV-Delta.03.00.00.bin |
| UCSB-PSU-2500ACDV-AA26870L-A | 05.0b | cmc-psuDV-Emerson.05.0b.bin |

IMM infrastructure firmware bundle contains the following images for Cisco UCS 6400 Series FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCS-FI-6454 | 10.5(1)I60(1a) | ucsfi.10.5.1.I60.1a.F.bin |
| UCS-FI-64108 | 10.5(1)I60(1a) | ucsfi.10.5.1.I60.1a.F.bin |
| UCS-IOM-2204XP | 4.3(6b) | chassis_soquel.img |
| UCS-IOM-2208XP | 4.3(6b) | chassis_soquel.img |
| UCS-IOM-2408 | 6.0(1a) | chassis4.img |

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCSBX-I-9108-25G | 6.0(1a) | chassis5.img |
| UCSX-I-9108-25G | 6.0(1a) | chassis5.img |
| UCSB-PSU-2500ACDV-ECD15020029 | 03.00.00 | cmc-psuDV-Delta.03.00.00.bin |
| UCSB-PSU-2500ACDV-AA26870L-A | 05.0b | cmc-psuDV-Emerson.05.0b.bin |

IMM infrastructure firmware bundle contains the following images for Cisco UCS X-Series Direct FI:

| Component | Packaged Version | Firmware Name |
|---|---|---|
| UCSX-S9108-100G | 10.5(1)I60(1a) | ucsfi.10.5.1.I60.1a.F.bin |
| UCSX-S9108-100G | 6.0(1a) | ucs-manager-k9.6.0.1a.bin |
| UCSBX-I-9108-25G | 6.0(1a) | chassis5.img |
| UCSX-I-9108-25G | 6.0(1a) | chassis5.img |
| UCSX-I-9108-100G | 6.0(1a) | chassis5.img |

# Deprecated Hardware

**Release 6.0(1)**

Beginning with Intersight Infrastructure Firmware Release 6.0(1), the following hardware is no longer supported:

- IOM Models:
  - UCS-IOM-2208XP
  - UCS-IOM-2204XP
  - UCS-IOM-2304
  - UCS-IOM-2304V2
- FEX Models:
  - N2K-C2232PP-10GE